



FLIGHTLINE GRAPHICS

Paint Masks - Stencils - Dry Rub Decals - Waterslides

Telephone: +44(0)7872 181119 (mobile)


Website: <http://www.flightlinegraphics.com>

email: sales@flightlinegraphics.com

A, C & D Roundel White First Supplementary notes.

Painting A, C, & D roundels requires blue, white, and red to be applied to surfaces that themselves can vary from white all through to black, so it is preferable to follow good practice and paint the lighter colours first before progressing to the darker shades. This supplementary instruction sheet gives guidance on how to paint roundels that have a dark outer and inner colours with a light middle circle using the minimum of paint. This simulation shows a C roundel, but the A & D roundel follow the same procedure.


Read these instructions in conjunction with the basic instructions available online – [click here](#).



As the title for the procedure suggests the white colour is sprayed first.

Position the "A" mask on the model following the normal procedures ensuring the 2 registration marks are located with dots or pins (see instructions: Paint Masks – The Basics)


The "A" mask will not be removed until after the blue colour has been applied!!



Apply white paint to the centre of the mask to a diameter slightly large than the disk of the "B" mask.


Take care not to over apply white on the outer edges as this could cause a white "tide mark" to the outer edge of the blue circle!

DO NOT REMOVE THE "A" MASK!




When the white paint has dried sufficiently apply the "B" mask using the registration disks for guidance.

Remove the "B" mask Registration Disks before painting.



Apply the blue colour to exposed areas.

When the blue paint has dried sufficiently the "A" & "B" masks can be removed



Apply the "C" mask and paint the red circle at the centre.

When the paint has dried sufficiently you can remove the mask and registration pins/dots whichever have been used.



And there you have the C roundel applied with the minimum of paint.

Remember the A & D mask is the same procedure, but the spacing between each colour is 1:1:1

Support : support@flightlinegraphics.com

Thank you.

Nigel Wagstaff
<http://www.flightlinegraphics.com/>